



DETAIL NAME:


TEE BEARING ON WALL BY OTHERS

DRAWN BY:
STAFF

CHECKED BY:
STAFF

DATE:

STANDARD DETAIL NUMBER:
5.3.1.1.71.01





DETAIL NAME:


TEE BEARING ON INVERTED TEE BEAM

DRAWN BY:
STAFF

CHECKED BY:
STAFF

DATE:
05/20/2022

STANDARD DETAIL NUMBER:
5.3.1.1.73.01





DETAIL NAME:


TEE BEARING ON LEDGER BEAM

DRAWN BY:
STAFF

CHECKED BY:
STAFF

DATE:

STANDARD DETAIL NUMBER:
5.3.1.1.73.02






DETAIL NAME: **TEE BEARING ON RECTANGULAR BEAM**

DRAWN BY:
STAFF

CHECKED BY:
STAFF

DATE:

STANDARD DETAIL NUMBER:
5.3.1.1.73.03





DETAIL NAME:


TEES AT EXPANSION JOINT BEARING ON DOUBLE BEAM AND COLUMN LINES

DRAWN BY:
STAFF

CHECKED BY:
STAFF

DATE:

STANDARD DETAIL NUMBER:
5.3.1.1.73.98





DETAIL NAME:


TEE BEARING ON RECTANGULAR BEAM WITH SLIP CONNECTION

DRAWN BY:
STAFF

CHECKED BY:
STAFF

DATE:

STANDARD DETAIL NUMBER:
5.3.1.1.73.99





DETAIL NAME:

TEE BEARING IN POCKET OF WALL PANEL SOLID WALL OR STRUCTURAL WYTHE


DRAWN BY:
STAFF

CHECKED BY:
STAFF

DATE:

STANDARD DETAIL NUMBER:

5.3.1.1.74.01





DETAIL NAME:


TEE BEARING IN POCKET OF WALL PANEL INSULATED PANEL AT THIN WYTHE

DRAWN BY:
STAFF

CHECKED BY:
STAFF

DATE:
03/07/2023

STANDARD DETAIL NUMBER:
5.3.1.1.74.02





DETAIL NAME:

TEE BEARING ON BUTTON HAUNCH SOLID WALL OR 6" STRUCTURAL WYTHE

DRAWN BY:
STAFF

CHECKED BY:
STAFF

DATE:
10/07/2022

STANDARD DETAIL NUMBER:
5.3.1.1.74.03

